

# OWNER'S MANUAL

---

## Electronic Torque Wrench

266 Series



CE


## Dear Users,

Thank you for purchasing our electronic torque wrench. This manual will help you to use the many features of your new electronic torque wrench. **Before operating the torque wrench, please read this manual completely**, and keep it nearby for future reference.

## MAIN FEATURES

- Head Interchangeable
- Electronic torque value readout
- +/- 1% or +/-2% accuracy
- CW and CCW operation
- Peak hold and track mode selectable
- Buzzer and LED indicator for the 9 pre-settable target torques
- Engineering units(N-m, ft-lb, in-lb, kg-cm) selectable
- 50 or 250 data memory for recall and joint torque auditing
- Auto Sleep after about 5 minutes idle
- Both AA and rechargeable batteries are compatible (batteries not included).

## NAMES AND FUNCTIONS OF PARTS



- |                              |   |
|------------------------------|---|
| 1. Round Head Ratchet Insert | 12. Torque Value                        |
| 2. Sensor Yoke               | 13. Pre-setting number                  |
| 3. LCD Display               | 14. Units(N-m, ft-lb, in-lb, kg-cm)     |
| 4. Buzzer                    | 15. P(Peak hold mode) /T(Track mode)    |
| 5. Communication Port        | 16. Power on/Clear button               |
| 6. Buttons                   | 17. Pre-setting number selection button |
| 7. Battery Compartment       | 18. Unit/Setting button                 |
| 8. Battery Cover             | 19. Up/Down button                      |
| 9. Ratchet Drive             |   |
| 10. Handle                   |   |
| 11. LED Indicator            |   |

# SELECTION GUIDE

, 1       , 2     , 3  
**MODEL NO:**

<b>266 1.5~30</b> <b>266 6.8~135</b> <b>266 10~200</b>	<b>A</b> <b>B</b>	<b>N</b> <b>U</b>
--	----------------------	----------------------

, 1 :

Model	Square drive (inches)	Max. Torque
266 1.5~30	1/4	30 N-m / 22.12 ft-lb / 265.5 in-lb / 306.1 kg-cm
266 6.8~135	1/2	135 N-m / 99.5 ft-lb / 1195 in-lb / 1378 kg-cm
266 10~200	1/2	200 N-m / 147.5 ft-lb / 1770 in-lb / 2041 kg-cm

, 2 :

Torque Accuracy	
<b>A</b>	+/-1%-CW / +/-2%-CCW
<b>B</b>	+/-2%-CW / +/-3%-CCW

, 3 :

Communication	
<b>N</b>	<b>No</b>
<b>U</b>	<b>Yes</b>

# SPECIFICATIONS

Model No.	Max. Torque (N-m)	Square Drive (inches)	Torque Measuring Range (N-m)	Length (mm)
266 1.5~30	30	1/4	1.5~30	390
266 6.8~135	135	1/2	6.8~135	410
All Models				
Torque Accuracy *1	BU			
	CW : ±2% CCW : ±3%			
Data memory size	250			
PC Connectivity *2	Yes			
Pre-setting No.	9 sets			
Bright LED	12LEDs (2 Red+10 Green)			
Operation Mode	Peak Hold / Track			
Unit Selection	N-m, ft-lb, in-lb, kg-cm			
Head Type	Round Head Ratchet Insert			
Size of Head of End Fitting (WxH)	9 × 12 mm			
Axial Distance	17.5 mm			
Gear Teeth	52			
Button	5			
Battery *3 (not included)	AA x 2			
Operating Temperature	-10°C ~60°C			
Storage Temperature	-20°C ~70°C			
Humidity	Up to 90% non-condensing			
Drop Test	1 m			
Vibration Test *4	10G			
Environmental test *5	Pass			
Electromagnetic compatibility test *6	Pass			

**NOTE: Accuracy is guaranteed from 20% to 100% full scale.**

\* : See note on page 5

## SPECIFICATIONS

Model No.	Max. Torque (N-m)	Square Drive (inches)	Torque Measuring Range (N-m)	Length (mm)
266 10~200	200	1/2	10~200	520
<b>All Models</b>				
Torque Accuracy *1	BU			
	CW : ±2% CCW : ±3%			
Data memory size	250			
PC Connectivity *2	Yes			
Pre-setting No.	9 sets			
Bright LED	12LEDs (2 Red+10 Green)			
Operation Mode	Peak Hold / Track			
Unit Selection	N-m, ft-lb, in-lb, kg-cm			
Head Type	Round Head Ratchet Insert			
Size of Head of End Fitting (WxH)	14 × 18 mm			
Axial Distance	25 mm			
Gear Teeth	52			
Button	5			
Battery *3 (not included)	AA x 2			
Operating Temperature	-10°C ~60°C			
Storage Temperature	-20°C ~70°C			
Humidity	Up to 90% non-condensing			
Drop Test	1 m			
Vibration Test *4	10G			
Environmental test *5	Pass			
Electromagnetic compatibility test *6	Pass			

**NOTE: Accuracy is guaranteed from 20% to 100% full scale.**

\* : See note on page 5


**Note:**

- \*1: The accuracy of the readout is guaranteed from 20% to 100% of maximum range + /- 1 increment. The torque accuracy is a typical value. Calibration line is at the middle line of the dark spot on the rubber handle. For keeping the accuracy, calibrate the wrench for a constant period time (1 year). And the accuracy is based on the zero degree of offset from perpendicular drive.
- \*2: Use a special designed cable (accessory) to upload record data to PC.
- \*3: Two AA batteries (Toshiba carbon-zinc battery)
- \*4: Horizontal and vertical test
- \*5: Environmental test:
  - a. Dry heat
  - b. Cold
  - c. Damp heat
  - d. Change of temperature
  - e. Impact (shock)
  - f. Vibration
  - g. Drop
- \*6: Electromagnetic compatibility test:
  - a. Electrostatic discharge immunity (ESD)
  - b. Radiated susceptibility
  - c. Radiated emission


## BEFORE USING THE WRENCH

### BATTERY INSTALLATION

- Remove the battery cap.
- Insert two AA batteries matching the -/+ polarities of the battery to the battery compartment.
- Put on the battery cap and rotate it tightly according to the following figures.



Direction of Battery and Cap Installation



### POWER ON AND RESETTING THE WRENCH

- Press **C** to power on the electronic torque wrench.
- Usually press **C** to reset the electronic torque wrench before using it.



#### ATTENTION:

If an external force is applied to the torque wrench during power-on/reset or wake up period, an initial torque offset will exist in the memory.

## ACTIVATION DURING SLEEP MODE

- The wrench will auto sleep after about 5 minutes idle for power saving. Press **(C)** to wake up the wrench during the sleep mode.

## CAUTIONS:

During communication period (**Send** appears), the sleep function is disabled.

## RESETTING THE WRENCH

- Press **(C)** **(^)** together will reset the wrench.
- If the wrench does not function normally, Press **(C)** **(^)** together to reset the wrench.


## LOW BATTERY VOLTAGE PROTECTION

- If the battery serial voltage is in low voltage status, the wrench will display a battery symbol and then turn off after a while.



## WHEN CHANGING THE TYPE OF HEAD

- If you use the different head of the wrench, the reading on the display will be different for the different length of the head. Please refer to the following explanation.



$$D = D1 * (L3+L1) / (L3+L2)$$

D : The set torque

D1: The actual torque applied to the nut.

L1: The extended length


L2: The normal length

L3: The length from the fitting pin to the calibration point.

- Reference dimension for each model :


Model	L2(mm)	L3(mm)
266 1.5~30	29	272.7
266 6.8~135	29	287.7
266 10~200	40	381.2

# SETUP




- ① Power On/Clear
- ② Unit Selection/Setting
- ③ Up/Down Button
- ④ Pre-Setting No.

## STEP 1: PRE-SETTING NO.




1. If **Er0** is appeared, that means this wrench has ever been applied more than 110% of torque of the spec.
2. The maximum capacity for “Pre-setting No.” is 9 sets.
3. The “Pre-setting No.” is cyclic.

## STEP 2: UNIT SELECTION




## STEP 3: SET TORQUE VALUE



**Note:**

1. The “Unit Selection” is cyclic.

## STEP 4: PEAK HOLD /TRACK MODE SELECTION




**Note:**

1. Please skip this procedure and continue to the next step.




# PEAK HOLD MODE OPERATION



Note:

1. If **Er0** is appeared, that means this wrench has ever been applied more than 110% of torque of the spec.
2. If **Full** is appeared, that means the wrench's memory is full and the next value record can not be written in. Please refer the "Peak Hold Mode Recorded Value Review" section to clear the memory records.
3. When 80% of the target torque is reached, the green LED will begin to flash and the alarm tone will beep intermittently.
4. When the target torque is approached, the alarm will change to a steady tone and the green LED will stop flashing and stay on. The red LED will also illuminate.

## Peak Hold Mode Recorded Value Review



**Note:**

1. The “Peak Hold” mode recorded value review also can be operated from “Track” mode operation.
2. If you operate in the “Peak Hold” mode, the display will show `none` and please go to next step.
3. If the record is empty, it will show `none`.
4. This function is not supported on all type of models.
5. Communication mode is for uploading record data to PC.
6. Communication mode is also for calibration of torque wrench. Please contact your local dealer for more information.

# COMMUNICATION




## Precaution:

1. **Communication function is only supported on some models. Check the model no. and its specification before using communication function.**
2. **Do not insert the plug of communication cable into torque wrench that does not support communication function.**

## CONNECTING COMMUNICATION CABLE

- Turn off power and then connect the accessory cable between the COM port of PC and torque wrench.



## UPLOADING RECORD DATA

- Make sure the connection between PC and wrench is normal.
- Press **C** **▲** together to reset the wrench.
- Change the wrench operation mode to **Send**.  
(Refer to “Peak Hold Mode Recorded Value Review” section)
- Use PC to start the uploader program.
- In uploader program, first select the correct COM port No.
- Next, select the file path to save the uploaded data.
- Finally, press “upload” button to transmit the torque records to PC.
- The uploaded data is then shown on the column and saved in the \*.csv file. Use Microsoft Excel to view \*.csv file.



## CAUTIONS:

**Refer to the uploader program user guide for the detail operations.**

## MAINTENANCE AND STORAGE

### ATTENTION:

**One-year** periodic recalibration is necessary to maintain accuracy.  
Please contact your local dealer for calibrations.

### CAUTION:



1. **Over-torque (110% of Max. torque range) could cause breakage or lose accuracy.**
2. Do not shake violently or drop wrench.
3. Do not use this wrench as a hammer.
4. Do not leave this wrench in any place exposed to excessive heat, humidity, or direct sunlight.
5. Do not use this apparatus in water.(not waterproof)
6. If the wrench gets wet, wipe it with a dry towel as soon as possible. The salt in seawater can be especially damaging.
7. Do not use organic solvents, such as alcohol or paint thinner when cleaning the wrench.
8. Keep this wrench away from magnets.
9. Do not expose this wrench to dust or sand as this could cause serious damage.
10. Do not apply excessive force to the LCD panel.
11. Apply torque slowly and graspe the center of the handle. Do not apply load to the end of handle

## BATTERY MAINTENANCE

1. When the wrench is not used for an extended period of time, remove the battery.
2. Keep a spare battery on hand when going on a long trip or to cold areas.
3. Do not mix battery types or combine used batteries with new ones.
4. Sweat, oil and water can prevent a battery's terminal from making electrical contact. To avoid this, wipe both terminals before loading a battery.
5. Dispose of batteries in a designated disposal area. Do not throw batteries into a fire.

Rev. : 266 1.0

